



Most of the new Swift models are now equipped with a driver assist package including a radar device mounted just behind the grill.

If this is damaged or the mountings bent then it requires calibrating. Suzuki dealers now have the tool required to enable this.

You may need to allow for the additional cost of this calibration.

Suzuki New Zealand Limited | 1 Heads Road | Wanganui 4500  
Private Bag 3008 | Wanganui Mail Centre | Wanganui 4541  
[www.suzuki.co.nz](http://www.suzuki.co.nz)