

Aftersales 2025- R4852 RG Colorado Structural Parts Restriction



Updated Date: 08/04/25, 03:26 PM GMT+12

RG Colorado Structural Parts Restriction

Bulletin number:	Aftersales 2025-R4852
Bulletin date:	08/08/2025
Contact person:	Dave Crook david.crook@gm.com
Who is this communication for?	Service, Parts & Collision Repair Industry

THIS DOCUMENT REPLACES ALL PREVIOUS BULLETINS ON THIS SUBJECT

Summary

This bulletin is to advise of CHANGES to the availability of certain Chassis Service Parts for the Holden RG Colorado which are also published in EPC. These Structural components will be restricted in SALE from GM ANZ directly to ONLY current GM Certified Collision Repairers who have satisfactorily completed the required Colorado Chassis welding training. These parts will no longer be able to be purchased by Holden Service & Parts agents.



Information

Chassis service replacement parts have been released for the RG Colorado & accordingly GM Australia & New Zealand (GMANZ) is taking steps to ensure that repairs to the chassis structure are completed by capable repairers with the proper training, tools and equipment.

Collision repairers that are a part of the Australian GM Certified Collision Repair Network (GM CCRN) will be the only shops permitted to purchase these restricted structural parts directly through GM ANZ in Australia.

These new Chassis Service parts will be treated as Restricted Parts. The following images show the components of the frame assembly that will be on parts restriction.

EPC will be updated with this information also.



The detail of information required to place an order & the list of current parts affected is included in the attachment “RG CHASSIS Parts Restriction-GMANZ_2025”.

GM CCRN Repairers should place the order with GM ANZ through their existing Direct Supply channel with GM ANZ.

The attached document “RG CHASSIS Parts Restriction-GMANZ_2025” contains some FAQ, the steps required for GM Certified Repairers to source these restricted parts as the need arises, as well as the current list of affected Parts numbers. That document can be shared freely & is also available on the Holden & GM Trade Parts websites.

Please note that any orders received for these Restricted Parts or supersessions from a Holden Service & Parts outlet or GMSV Dealer will be rejected and not filled.

RG Colorado Restricted Parts List

Please note that part numbers may change, and parts may be added to this list at any time. Supersessions to & from Part Numbers in this list will also be included as Restricted Parts.

GM PART #	GM PART DESCRIPTION
92510895	CROSSMEMBER ASM SPA WHL HOIST
92510897	CROSSMEMBER ASM SPA WHL HOIST
92510903	MOUNT RR S ABS
92510905	MOUNT RR S ABS
95711901	BRACKET BODY RR MT
95711902	BRACKET BODY MT
95711903	BRACKET BODY FRT MT
95711904	BRACKET BODY RR MT
95711905	BRACKET BODY RR MT
92510923	CROSSMEMBER ASM FRT
92510925	CROSSMEMBER ASM RR
95711900	CROSSMEMBER ASM RR
92510891	BRACKET ASM-FRT BPR IMP BAR
92510893	BRACKET ASM-FRT BPR IMP BAR
92510899	BRACKET ASM-FRT BPR IMP BAR
92510901	BRACKET ASM-FRT BPR IMP BAR
92512948	COUPON KIT
95711822	COUPON KIT

Authorised by: Jesse Pope - General Manager, Aftersales Business Development

[Aftersales 2025-R4852 RG Colorado Structural Parts Restriction.pdf](#)

[RG CHASSIS Parts Restriction-GMANZ_2025.pdf](#)

About this Article

Reference Number: 12924

Published To: Service, Home, Parts

Version: 1.0

Original Published Date: 08/08/25, 09:00 AM GMT+12

Expires: 08/08/27, 01:59 AM GMT+12

